FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer) (Re: G.O Ms. 20/70/PWD Dt. 23-01-1970)

Name of Officer

: MALINI K

Name of School

: A E T ENGLISH MEDIUM SCHOOL

Location/with name of Education

AMAYUR PATTAMBI

District/Sub District

: Pattambi, Ottappalam, Palakkad

Classification of building and size

: Detailed Measurment attached seperatel

Period of which the certificate issued

: 2025-2026

Nature of defects if any

Foundation and basement:

Superstructure

: nil Doors & windows

Wood work wrought

: nil and put up : nil

Roof

: nil Flooring

Miscellaneous (cracks etc): nil

Any major defects noticed which will hender the building unsafe in any manner : No Major defects noticed during inspection.

Whether maintenance works have been

Done properly

: Yes

Whether the structure is sound on for

Conducting classes

The structure is sound for conducting classes under normal wind and weather condition.

Note: 1. The stability of the structure should be examined also with reference to location, Attitude, intensity of wind, exposure to load etc.

2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 02/07/2025 and found to be fit to conduct classes for the period 2025-26 for the reasons noted above.

Place: Pattambi Date: 02-07-2025



M Signaldie LID & EW SECTION PATTAMBI MUNICIPALITY

BUILDING AREA DETAILS:

BLOCK A

Ground Floor

- 1. 6.10m x 6.10m x 6.10 x 3.60 m 5 Nos Class room
- 2. 34.45 m x 1.50 m x 1.50 m x 3.60 m Varandah
- 3. 6.10 m x 3.10 m x 3.10 m x 3.60 m Stair case

First Floor

- 1. 6.10 m x 6.10 m x 3.60 m 5 Nos Class room
- 2. 34.45 m x 1.50 m x 3.60 m Varrandah
- 3. 6.10 m x 3.10 m x 3.60 m Stair case

BLOCK B

Ground Floor

- 1. 6.10 m x 6.10 m x 3.60 m 5 Nos Class room
- 2. 31.60 m x 1.60 m x 3.60 m Varandah



MALTANA P.

PEN: 449342

PEN: 449442

PEN: 4